

C.L. "BUTCH" OTTER – Governor RICHARD M, ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6326 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

January 23, 2008

Debbie Henscheid, Administrator Fairwinds -- Sandcreek 3310 Valencia Drive Idaho Falls, ID 83404

License #: RC-661

Dear Ms. Henscheid:

On August 29, 2007, a Fire Life Safety Survey was conducted at Fairwinds -- Sandcreek. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level:

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire Safety and Construction Program, at (208) 334-6626.

Sincerely.

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

- mmille

EM/lj

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program

C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

September 7, 2007

Kelly Palmer, Administrator Fairwinds - Sandcreek 3310 Valencia Drive Idaho Falls, ID 83404

Dear Ms. Palmer:

On August 29, 2007, a Fire Life Safety Survey was conducted at Fairwinds - Sandcreek. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by September 28, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/li

Enclosure

(X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 01 - ENTIRE BUILDING A. BUILDING B. WING 08/29/2007 13R661 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 3310 VALENCIA DR **FAIRWINDS - SANDCREEK** IDAHO FALLS, ID 83404 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PRÉFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R 000 R 000 Initial Comments The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on August 29, 2007. The surveyor conducting the survey was: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety & Construction Program

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

## ASSISTED LIVING Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
Tais wives sanacreel	3510 Valoncia	542 6200
Administrator Kelly Palmer	Idah o Falls	2IP Code 85 404
Survey Team Leader  Eric Mundell	Survey Type	Survey Date 8/29/07
NON CODE ICCUTE		

Survey T	eam Leader	0	Survey Type	Survey Date	1				
	Eric Mundell FLS 8/		8/2	29/07					
NON-CORE ISSUES									
ITEM #	RULE# 16.03.22		DESCRIPTION	# 5 # 5 # 5 # 5 # 5 # 5 # 5 # 5 # 5 # 5	DATE RESOLVED	BFS USE			
/	4.5.03	Medical Gares: L	20 mid organ transfelling We floor it linderly and - Also the soem in not outside.	is done					
		in a room where of	he floor it linoleuth and	nut	_				
		coment/concrete/file	Also the room in not	meehaana	Uy .				
	***************************************	you trated to the	out side		V <sup>e</sup>				
			,						
						5.26.8			
						(CB 16) 76			
						99 dp 85 mg			
1	se Required Date	Signature of Facility Representative	,		Date Signed				
9/2	5/07	X Duly Heroch	od	:					